Thursday, April 15, 2004

To Whom It May Concern:

Intoxilyer 66-004814 was taken out of service for repair on 4/14/04.

I cannot testify that it was working properly and accurately between the dates of

3/14/04 and 4/14/04.

This instrument was located at the Traffic substation 7575 E. Speedway.

Irene Doran (46331) Intoxilyzer 5000 QAS Tucson Police Department Crime Lab 791-4494